

## Menu

HISTORY FILE MAP for year 2008


REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

Gaps in TM during period 016 – 021 resulted from multiple changes to the original DSN coverage due to having lost X-Band TM after TWTA1 failure to reacquire on day 015.



015:07:56-09:51 1h55m 128 bps data lost at DSS-54 after enabling S-Band TM due to having lost X-Band (TWTA1 failed to start). Problem with generation of S-Band tables for S/C ID (55). DR number pending.

015:15:03-17:19 2h16m 128bps data lost due to water leak in DSS-14 heat exchanger. Station had to be released to repair problem. DR G108281 refers.